Entry Point Monitoring Form



Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

THE OWNER OF THE OWNER, WHEN	рН	-	Phos	Other	Y/N
1	7.80				Y
2	7.78				Y
3	7.4				4
4	7.79				Ý
5	7.77				Y
6	7,54				YYY
7	7.63	5472			Y
8	7,54				Y
9	7.50				4
10	7.53				Y
11	7,67				4
12	7.66				Y
13	7,69	54.72			4
14	7.73				4
15	7.73	-			4
16	7.71				4
17	7,75				Y
18	7.68				7
19	7.74				Y
20	7.67				4
21	7.75	54.72	-		V
22	7.72				44
23	7,74				Y
24	7,74				V
25	7.74				4
26	7,67				V-Y-Y-Y-
27	7.71	54.72			4
28	7.69				4
29	7,74				4
30	7,66				Y
31					1
	l = Exc	ursion	Tota	N's	A
					4

< <have< th=""><th>County: Tillamook Agency: REGION 1</th></have<>	County: Tillamook Agency: REGION 1
minimums	ENTRY POINT
been met for this day?	EP-A
	PWS ID 4100556
NE	TARTS WATER DISTRICT
Sample pe	eriod: NOVEMBER 2023

Number of excursions during this month:

Month/Year

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

pH 7.4
•
Alk 40.0 (Alkalinity)

Print Name: DAVID Harrock

Signature: Ward Harrock

Date & Phone#: 12/4/23

Send to DWP within 10 days after end of

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/