Entry Point Monitoring Form



Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	7.97				
2	8.00				
3	7.96				
4	8,07				
5	8.00				
6	8,00	47.88			
7	8,01				
8	7.91				
9	7.95				
10	8.06				
11	7.99				
12	7,99				
13	7.92				
14	7.78	47,98			
15	7.99				
16	7,98				
17	8,00				
18	8,00				
19	8,02				
20	7.59	47.88			
21	7.63				
22	7.63				
23	7.69				
24	7.65				
25	7.69				
26	7,70				
27	7.71	47.88			
28	7.67				
29	7.67				
30	7.69				
31	7.71				
Vo = I	V = Exc	cursion) Tota	l N's	0

< <have< th=""><th>County: Tillamook Agency: REGION 1</th></have<>	County: Tillamook Agency: REGION 1
minimums	ENTRY POINT
been met for this day?	EP-A
	PWS ID 4100556
NE	TARTS WATER DISTRICT
Sample pe	eriod: 5/2024 MAY Month/Year

Number of excursions during this month: ___

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

	um Water Quality neter(s) as set by State:
pH Alk	7.4 40.0 (Alkalinity)

 Print Name: Day D. Hancoc

 Signature:
 1

 Date & Phone#:
 6/5/24
 971.241.725

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/