NETARTS WATER DISTRICT Entry Point Monitoring Form 41-0556

Entry Point Monitoring Form



Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	7.81				
2	7.71				
3	7.67	47.88			
4	7.67				
5	7.64				
6	7.63				
7	7.62				
8	7.60				
9	7.62				
10	7.57	47,88			
11	7,55	•			
12	7,57				
13	7,59				
14	7,59				
15	7.60				
16	7.59				
17	7.62	47,6			
18	7.59				
19	7,59	-			
20	7.60				
21	7,62				
22	7.60				
23	7,64				
24		47,88			
25	7,60				
07	7,59				
00	7.62				
28	7.62				
29	7.62				
30	7,62				
31					
lo = N	= Exc	ursion)	Total	N's	8
				The same	THE RESERVE

< <have< th=""><th>County: Tillamook Agency: REGION 1</th></have<>	County: Tillamook Agency: REGION 1
minimums been met for	ENTRY POINT
this day?	EP-A
	PWS ID 4100556
NE	TARTS WATER DISTRICT
Sample pe	eriod: June 2024
	Month/Year

Number of excursions during this month: _

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

		ater Quality) as set by State:
pH Alk	7.4	(Alkalinity)

Print Name: DAVID Hane Signature: Way (Date & Phone#: 07/01/24 Send to DWP within 10 days after end of 971.241.7203 sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/