Entry Point Monitoring Form



Water Quality Parameter Monitoring Form **Lead & Copper Rule Corrosion Control**

Day	рН		Phos	Other	Y/N
.1	760	x2.98			Y
2	7.64				Y
3	7,64				4
4	7.65				Y
5	7,42				Y
6	7.62				Y
7	7.62				M
8	7.72	到和			Y
9	7.77				4
10	7.77				Y
11	7.81				4
12	7.89				4
13	7.84				Y
14	7.84				4
15	7.86				Y
16	7,88	54.72			4
17	7.86				4
18	7.89				4
19	7.89				4
20	7.84				4
21	7.86				4
22	8.37	100			4
23		54.72			Y
24	7,84				4
00	7,89	-			4
	7.87				4
	7.89				1
	7,74	- 16			Y
	7.76	34,72			4
30	7.72				
31	7.71			1	1
o = N	= Excu	ursion)	Total	N's	0

< <have< th=""><th>County: Tillamook Agency: REGION 1</th></have<>	County: Tillamook Agency: REGION 1				
minimums been met for	ENTRY POINT				
this day?	EP-A				
PWS ID 4100556 NETARTS WATER DISTRICT					
Sample pe	eriod: July 2024				

Number of excursions during this month:

"(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

– Keīerence –	
	um Water Quality leter(s) as set by State:
pH [Alk [7.4 40.0 (Alkalinity)
Print Name: _	DAVID Hangock
Ciamata	11/2 // 1</td

Signature: _ Date & Phone#: Send to DWP within 10 days after end of

sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/