Entry Point Monitoring Form



Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	8.08				
2	8.17				
3	8.17				
4	8.24				
5	8.17				
6	8.17				
7	8.20	547			
8	8.13				
9	8.13				
10	8.15				
11	8.18				
12	8.27				
13	8.17	547			
14	8.18				
15	7.64				
16	7.81				
17	7.74				
18	8.18				
19	7.81				
20	7.88				
21	7.84	54.7			
22	7.81				
23	7.88				
24	7.88				_
25	8.05				
26	7.96				_
27	7.91				_
28	7.91				
29	7.95	41.1			
30	7.98				
31	7.50				
No=	N = Ex	cursior)Tota	al N's	0

< <have< td=""><td>County: Tillamook Agency: REGION 1</td></have<>	County: Tillamook Agency: REGION 1
minimums	ENTRY POINT
been met for this day?	EP-A
	PWS ID 4100556
NE	ETARTS WATER DISTRICT
Sample pe	eriod: October /2024
	Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Print Name:					
Signature: _	gC.	and?	& James		
Date & Phon	e#:	11/4/2	4 9	71-241-	7203
Send to DWF					

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

sampling period