Entry Point Monitoring Form



Water Quality Parameter Monitoring Form **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1	7,52		(8)		
2	7.48				
3	7.50				
4	7,50	54.7			
5	7.51				
6	7.53				
7	7.55				
8	7.57				
9	7.59				
10	7,60				
11	7.60				
12	7,40	47.9			
13	7.89				
14	7.85				
15	7.93				
16	7.98				-
17	7.91		-		-
18	7,65	41.04	1	-	-
19	7.47	_			+
20	7.4=	7			-
21	7.76			-	-
22	77	1			-
23	7.74	/	-	-	
24	7.74			-	
25	7.7)	41.0	1		
26	7.7				
27	7.7	1			
28	7.1	7			
29	111				
30	_	/			
31					
(No=	N=E	xcursic	n) Tot	al N's	50

< <have< th=""><th>County: Tiliamook Agency: REGION 1</th></have<>	County: Tiliamook Agency: REGION 1
minimums	ENTRY POINT
been met for this day?	EP-A
-	PWS ID 4100556
NE	TARTS WATER DISTRICT
Sample pe	eriod: NOVEMBER 2024
Oddino.	Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

pH 7.4 Alk 40.0 (Alkalinity)	um Water Quality neter(s) as set by State:

Print Name: DAVID Signature: 15 Date & Phone#: 12/6

Send to DWP within 10 days after end of

sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/