## Entry Point Monitoring Form



## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N	
1	7.85					
2	7.83	41.04				
3	7,84					
4	7.84					
5	7.88					
6	7.86					
7	7,88					
8	7,86					
9	7,84					
10	7.84					
11	7.83					
12	7.84					
13	7.88					
14	7.88					
15	7.89					
16	7.89					
17	7.89		i			
18	7.89	3				
19	7.89					
20	7.89					
21	7.80	7				
22	7.91					
23	7.91	1				
24	7.7					
25	7.7					
26	7.62					
27	7.2					
28	11.11	68,1	+			
29						
30	7.91	41.0	4			
31	1					
(No = N = Excursion) Total N's						

< <have< td=""><td>County: Tillamook Agency: REGION 1</td><td></td></have<>	County: Tillamook Agency: REGION 1					
minimums	ENTRY POINT					
been met for this day?	EP-A					
	PWS ID 4100556					
NETARTS WATER DISTRICT						
Sample pe	eriod: 12/2024  Month/Year					

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Print Name:	DAV	D B	Hanco	KA	
Signature:	Van	1 7	2/ mese	P	
Date & Phon	ne#:	01/0	2/25	503	842-9405
Send to DWF	o withi				

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/