## Entry Point Monitoring Form



## Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	791				
2	2.91				
3	7.91				
4	7.91				
5	741				
6	7,74	47.9			
7	7,98				
8	7,92				
9	7,86				
10	7 96				
11	796				
12	7,96				
13	7.91	97.9			
14	7.91				
15	8.42				
16	8,95				
17	7.71				
18	7.83				
19	8,54				
20	8,97				
21	8.46	97.9			
22	8,46				
23	9,27				
24	8,97				
25	9.66				
26	9.88				
	8.42				
28	8,42	47.9			
29	11.57				
30	11.16				
31	10,03				
10 = N	l = Exc	ursion	Tota	l N's	Ø

< <have minimums<="" th=""><th>County: Tillamook Agency: REGION 1  ENTRY POINT</th></have>	County: Tillamook Agency: REGION 1  ENTRY POINT
been met for this day?	EP-A
	PWS ID 4100556
NI	TARTS WATER DISTRICT
Sample pe	eriod: JANHARY 2025
	Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

	um Water Quality seter(s) as set by State:
pH ] Alk ]	7.4 40.0 (Alkalinity)
rint Name:	DAVID HANCOCKS

Print Name: _	DAVID HANCOCKS	
Signature:	Dona Allan	ude
Date & Phone	#: 02/03/25	971-241-720=
Send to DWP	within 10 days after en	nd of

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

sampling period

Deference