

Entry Point Monitoring Form



Water Quality Parameter Monitoring Form  
**Lead & Copper Rule Corrosion Control**

Day	pH	Alk	Phos	Other	Y/N
1	10.20				
2	10.29				
3	10.63	47.9			
4	10.96				
5	10.19				
6	10.37				
7	7.00				
8	7.59				
* 9	7.06				
10	7.77	47.9			
11	7.77				
12	7.77				
13	7.76				
14	7.76				
15	7.77				
16	7.76				
17	7.85				
18	7.62	47.9			
19	7.62				
20	7.62				
21	7.62				
22	7.62				
23	7.64				
24	7.64	47.9			
* 25	7.33				
26	8.58				
27	8.44				
28	8.30				
29					
30					
31					

(No = N = Excursion) Total N's 2

<<Have minimums been met for this day?	County: Tillamook Agency: REGION 1 <b>ENTRY POINT</b> EP-A PWS ID 4100556 NETARTS WATER DISTRICT Sample period: <u>FEBRUARY</u> Month/Year
--	--

Number of excursions during this month: 2

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative).  
An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference	
<b>Minimum Water Quality Parameter(s) as set by State:</b>	
pH	7.4
Alk	40.0 (Alkalinity)

Print Name: DAVID Hancock  
 Signature: *David Hancock*  
 Date & Phone#: 3/6/25

Send to DWP within 10 days after end of sampling period