Entry Point Monitoring Form



Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	8,15				
2	7.95	_			
3	7.88	40.8			
4	7.78				
5	7.74				
6	7.72				
7	7.67				
8	7164				
9	7.64				
10	7.71				
11	7,71	41.04			
12	7.71				
13	7.71				
14	7.71				
15	7.71				
16	7.67				
17	7.67	A1,04			
18	7.67				
19	7,67				
20	7,67				
21	7.21	•			
22	7.81				
23	7.91				
24	7.67	u7.98			
25	7,65				
26	7,60	,			
27	7.59	,			
28	7.62	7.			
29	7,62	٠.			
30	7.85	F			
31	7.55				No may think
Vo = I	N = Ex	cursion)Tota	l N's	0

< <have< th=""><th>County: Tillamook Agency: REGION 1</th></have<>	County: Tillamook Agency: REGION 1
minimums	ENTRY POINT
been met for this day?	EP-A
	PWS ID 4100556
NE	TARTS WATER DISTRICT
Sample pe	eriod: MARCH / 2025 Month/Year

Number of excursions during this month: ____

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

	um Water Quality neter(s) as set by State:
pH Alk	7.4 40.0 (Alkalinity)
rint Name	DAVID R HANCOCK

Print Name: DAVID B HANCOCK
Signature: Dond R/mwdk
Date & Phone#: 971-241-7203

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/