

Entry Point Monitoring Form



Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Other	Y/N
1	7.89	41.04			
2	7.89				
3	7.88				
4	7.86	47.88			
5	7.84				
6	7.83				
7	7.77	47.88			
8	7.77				
9	7.77				
10	7.78				
11	7.74				
12	7.77				
13	7.77				
14	7.62	47.88			
15	7.64				
16	7.64				
17	7.64				
18	7.64				
19	7.65				
20	7.65				
21	7.67	47.88			
22	7.67				
23	7.67				
24	7.71				
25	7.76				
26	7.81				
27	7.84				
28	7.86	47.88			
29	7.86				
30	7.88				
31					

(No = N = Excursion) Total N's ☒

<<Have
minimums
been met for
this day?

County: Tillamook Agency: REGION 1

ENTRY POINT

EP-A

PWS ID 4100556

NETARTS WATER DISTRICT

Sample period: APRIL 2025
Month/Year

Number of excursions during this month: _____

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative).
An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

Minimum Water Quality
Parameter(s) as set by State:

pH 7.4
Alk 40.0 (Alkalinity)

Print Name: NETARTS = DAVID Hancock

Signature: David Hancock

Date & Phone#: 5/5/25

Send to DWP within 10 days after end of
sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>