Entry Point Monitoring Form



Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	pН	Alk	Phos	Other	Y/N
1	7.84				
2	7.88				
3	7.91				
4	7.91				
5	7.96	41.04			
6	7.93				
7	7,77				
8	7.77				
9	7.82				
10	7.88				
11	7.69				
12	7.69	47.9			
13	7.67				
14	7.64				
15	7.64				
16	7.57				
17	7,57				
18	7.55				
19	7,53	47.9			
20	7.48				
21	7,50				
22	7,48				
23	7.47				
24	7.60				
25	7.47				
26	7.71				
27	7.91	41.04			
28	769				
29	7,67				
30	7,71				
31	7.81				

< <have< th=""><th>County: Tillamook Agency: REGION 1</th></have<>	County: Tillamook Agency: REGION 1				
minimums been met for	ENTRY POINT				
this day?	EP-A				
	PWS ID 4100556				
NE	TARTS WATER DISTRICT				
Sample period: June 2025 Month/Year					

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

	um Water Quality leter(s) as set by State:
pH [Alk]	7.4 40.0 (Alkalinity)
rint Name:	DAVID HANCOCK

Print Name: DAVID Hancock
Signature: Name # January
Date & Phone#: 6/2/25 971.247.7203

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/