## Entry Point Monitoring Form

## Health

## Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	pН	Alk	Phos	Other	Y/N	< <have< th=""><th>County: Tillamook Agency: REGION 1</th></have<>	County: Tillamook Agency: REGION 1	
1	7.9					minimums	ENTRY POINT	
2	7 95	-47,80				been met for		
_	7.77					this day?	EP-A	
	8.06						PWS ID 4100556	
	7.83					NETARTS WATER DISTRICT		
	7.84							
7	7.84					Number of excursions during this month:  (Over 9 excursions in 6 months is a violation. Entr. Point and Distribution excursions are cumulative).  An 'excursion' is any day in which the water qualit parameter(s) fall below the minimum set by the		
8	7.88							
	7.88	41.04						
_	7.88							
11	7.88							
12	7.89							
$\overline{}$	7.88							
	7.88							
_	7.81					State.		
	7.95							
-	8,05	41,50				Reference		
=	7.83							
_	7.36					Minimum Water Quality		
0	7.89					Pa	arameter(s) as set by State:	
1	7.91					pH 7.4		
2	7.91	do al					Alk 40.0 (Alkalinity)	
3	-	47.86						
24 :	7.81							
25	7.77							
6	7.7-7							
27	7.79			-		Print Name: Pavid Hancock		
8	7.83					Signatur		
29	7.83	112 01					hone#: 07/01/2025	
30	9,91	47.80				Send to [	DWP within 10 days after end of	
31				1	1			

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/