

Entry Point Monitoring Form



Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Other	Y/N
1	10.36	47.88			
2	10.07				
3	8.03				
4	8.06				
5	8.20				
6	8.10				
7	8.05				
8	7.98	47.64			
9	7.96				
10	8.00				
11	8.01				
12	8.03				
13	8.03				
14	8.03				
15	8.03				
16	7.98	47.48			
17	7.98				
18	8.01				
19	8.01				
20	8.01				
21	7.95				
22	7.81	41.04			
23	7.81				
24	7.81				
25	7.81				
26	7.88				
27	7.69				
28	7.91				
29	8.00	41.04			
30	8.00				
31					

(No = N = Excursion) Total N's

<<Have
minimums
been met for
this day?

County: Tillamook Agency: REGION 1

ENTRY POINT

EP-A

PWS ID 4100556

NETARIS WATER DISTRICT

Sample period: _____
Month/Year

Number of excursions during this month: _____

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative).
An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

**Minimum Water Quality
Parameter(s) as set by State:**

pH
Alk (Alkalinity)

Print Name: _____

Signature: _____

Date & Phone#: _____

Send to DWP within 10 days after end of
sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>