Entry Point Monitoring Form



Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

	*42.00			
7.76 7.93 0.56 10.76 8.00 7.96 7.98 7.93 7.93				
7.93 0.58 10.78 8.00 7.96 7.98 7.93 7.93				
7.93 0.58 10.78 8.00 7.96 7.98 7.93 7.93				
0.56 10.76 8.00 7.96 7.98 7.93 7.93				
10,78 9.00 7.96 7.98 8.15 7.93 7.93				
7.96 7.98 8.15 7.98 7.93 7.95				
7.98 7.98 7.93 7.95				
3,15 7,98 7,93 7,95				
7.93 7.95				
7.93				
7.95	.0.00			
	.000			
0.0	47,88			
8.12				
8112				
8.12				
8.10				
8.06				
2.05	-			
3.05	41.04			
7,96				
8.17				
8:10	54,72			
3,06				
-	8.01 7.93 7.83 7.84 7.96 8.17 8.10 8.32 8.20	8.0\ 7.93 7.83 7.84 7.96 8.17 8.10 \$4,70 8.32 8.23 8.17 8.104	8.0\ 7.93 7.83 7.84 7.96 8.17 8.10 \$4.70 8.32 8.22 8.17 8.104	8.01 7.93 7.83 7.84 7.96 8.17 8.10 \$1,72 8.32 8.20

< <have< th=""><th>County: Tillamook Agency: REGION 1</th></have<>	County: Tillamook Agency: REGION 1
minimums been met for this day?	ENTRY POINT
	EP-A
	PWS ID 4100556
NE	TARTS WATER DISTRICT
Sample pe	riod: October 2025
	Month/Year

Number of excursions during this month: _

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Print Name: DAVID Signature: _ Date & Phone#: 10 Send to DWP within 10 days after end of

sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/