

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Lincoln Agency: REGI</th></have<>	County: Lincoln Agency: REGI		
17	7.0				Y	minimums been met for this day?	ENTRY POINT		
7	7.0				4		EP-A		
12	7,0				4	tillo day :			
17	7,0	1			4	PWS ID 4100564 BAY HILLS WATER ASSOCIATION Sample period: May 202(Month/Year			
22	7,0				Y				
27	7,1				Y				
3 1									
					 		· · ·		
						Number of excursions during this month:			
					5	Point and D An 'excursion parameter(s State.	(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State. Reference Minimum Water Quality		
						Parameter(s) as set by State:			
							pH 7.0		
			1		-				
					1				
1									
							•		
						man (i) process and is shall reported by the original and support support and support support and support support and support support and support support and support and support and support and support and supp			
						Print Name: John MacKown			
		Signature: John Micken							
						Date: <u>6</u> -	-01-2/		
No = N	I = Excu	ursion)	Total	N's	0	Send to D' sampling p	WP within 10 days after end of period		

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: wwww.ohd.hr.state.or.us/dwp