

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Lincoln Agency: REGI</th></have<>	County: Lincoln Agency: REGI	
1	7.0				Y	minimums	ENTRY POINT	
6	7,0				4	been met for this day?	EP-A	
11	7.0				4	tino day .		
17	7.1	-			Y	PWS ID 4100564 BAY HILLS WATER ASSOCIATION		
22	4.0				Y			
27	7-1				Y	Sample period: June 21 Month/Year		
2.3								
						Number of excursions during this month:		
						(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State. Reference Minimum Water Quality Parameter(s) as set by State: pH 7.0		
,		945				Print Name: John MacKown Signature: Date: 1 Jul 21		
12	\							
10 = N	Send to DWP within 10 days after end of sampling period							

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp