

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Lincoln Agency: REGI</th></have<>	County: Lincoln Agency: REGI		
14	7.0				Y	minimums been met for this day?	ENTRY POINT		
10	7,2				Y		EP-A		
15	7.0				Y		PWS ID 4100564		
22	7-1				X	BAY HILLS WATER ASSOCIATION			
29	7.0				17				
	1					0	Sm 2/		
1,1						Sample period: SEP Z/ Month/Year			
							World Feat		
					,				
						Number of excursions during this month:			
				P.					
-					<u> </u>				
					3	State.			
						Refe	erence		
							Minimum Water Quality		
							Parameter(s) as set by State:		
					-		pH 7.0		
,3					-				
ì		-							
							a de la companya de		
						D.i. (N	Toba MacKawa		
						Print Name: John MacKown			
					-	Signature: John Mackour			
		L				Date: <u>/ </u>			
(No = N	(No = N = Excursion) Total N's Send to DWP within 10 days after end of								
sampling period									

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp