

## Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Lincoln Agency: REGI</th></have<>	County: Lincoln Agency: REGI	
1	7,0				Y	minimums been met for	ENTRY POINT	
5	7.1				Y	this day?	EP-A	
9	7,2				4		PWS ID 4100564	
18	7.2				X	The second secon		
24	7.4			-	4	BA	Y HILLS WATER ASSOCIATION	
			-			i i	1101121	
				100		Sample period: NOV 21  Month/Year		
				G.			Month/Year	
					,			
						Number of excursions during this month:		
						Point and E An 'excursi parameter(	cursions in 6 months is a violation. Entry Distribution excursions are cumulative). ion' is any day in which the water quality is) fall below the minimum set by the	
			-			State.		
						Refe	erence	
							Minimum Water Quality Parameter(s) as set by State:	
							pH 7.0	
-		-			-			
.1	-				-			
-	<del>                                     </del>							
Print Name: John MacKown				A				
							e: John Mackion	
						Date:	Dec 21	
(No = 1	No = N = Excursion) Total N's Send to DWP within 10 days after end of sampling period							

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp