

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Lincoln Agency: REGI</th></have<>	County: Lincoln Agency: REGI	
"/	7,0				4	minimums	ENTRY POINT	
10	700				4	been met for this day?	EP-A	
17	7.2				7		PWS ID 4100564	
25	7.4				4	BAY HILLS WATER ASSOCIATION		
31	710				4			
10							DEC 71	
						Sample period: DEC Z/ Month/Year		
				· 10				
				1	, ,		**	
						Number of excursions during this month:		
						(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative).		
						An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State. Reference		
					,			
							Minimum Water Quality	
						April 19 and 19	Parameter(s) as set by State:	
-							pH 7.0	
- 1			-		-		-	
-						10.00		
i								
							*	
						Print Name: John MacKown		
						Signature: Osla Mac You Date: 1 Jan 72		
						Date: /	1 KU 7 Z	
(No = N = Excursion) Total N's Send to DWP within 10 days after end of								
	sampling period							

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: wwww.ohd.hr.state.or.us/dwp