

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Lincoln Agency: REGI</th></have<>	County: Lincoln Agency: REGI	
7	7:0				4	minimums been met for this day?	ENTRY POINT	
15	7,0				7		EP-A	
23	7.0				4	uns day!		
30	7.0	X.			4	PWS ID 4100564 BAY HILLS WATER ASSOCIATION		
н.				i		Sample period: TAN ZZ Month/Year		
3.1								
				The state of the s	٠,		*	
						Number of excursions during this month:		
						(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative).		
						An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State. Reference		
			 		.*			
						disciplination of the state of	Minimum Water Quality	
						Parameter(s) as set by State:		
						2004	The second	
,						the debit over the second		
1								
-								
				•		Print Name: John MacKown		
						Signature: John Mackown		
						Date:/	OFeb 22	
(No = N	(No = N = Excursion) Total N's Send to DWP within 10 days after end of							
	sampling period							

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: wwww.ohd.hr.state.or.us/dwp