

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Lincoln Agency: REGI</th></have<>	County: Lincoln Agency: REGI	
6	7,0				Y	minimums	ENTRY POINT	
13	7:0				Y	been met for this day?	EP-A	
21	7,2				Y	Line day.	PWS ID 4100564	
27	7,1				У	DAY		
	,					BAY HILLS WATER ASSOCIATION		
							FFR 72	
g - k						Sample period: FEB ZZ Month/Year		
						1	IVIOTILITY I CAI	
						~		
						Number of excursions during this month:		
-								
-								
					,	State.		
						Refe	erence	
<u>.</u>							Minimum Water Quality	
							Parameter(s) as set by State:	
-							pH 7.0	
1	Windows				-			
1								
	D. COMMISSION OF THE PARTY OF T							
						D: (1)	Toka Mook own	
						Print Name: John MacKown Signature: Och Mickown		
						Date: 3-1-772		
		<u></u>				ک Date: <u>ک</u>	-1 + CC	
(No = N = Excursion) Total N's Send to DWP within 10 days after end of								
sampling period								

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp