

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Lincoln Agency: REGI</th></have<>	County: Lincoln Agency: REGI	
<u>~</u> 5	70				4	minimums	ENTRY POINT	
12	7.0				y	been met for	EP-A	
19	7,0				У	this day?		
26	7.0	4			Y		PWS ID 4100564	
	1/4					BA	AY HILLS WATER ASSOCIATION	
	i.							
						Sample period: MAR 2Z  Month/Year		
					<u> </u>		• *	
						Number of excursions during this month: O  (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative).		
						An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.		
-								
	<del></del>				1	Otato.		
-						D	5a wa wa a	
						Rei	ference	
							Minimum Water Quality	
							Parameter(s) as set by State:	
							pH 7.0	
							pi i	
- 1						14		
1								
					38	Print Name: John MacKown		
						Signature: Oh Muchan		
						Date: / Apr 22		
$(N_0 - N_1)$	= Evo	rcion)	Tatal	NII-	1			
(140 - 14	(No = N = Excursion) <b>Total N's</b> Send to DWP within 10 days after end of sampling period							

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: wwww.ohd.hr.state.or.us/dwp