

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day 7 15 22 29	pH 7,0 7,0 7,0 7,0 7,0 7,0	Alk	Phos	Sili	Y/N	Number of (Over 9 exc Point and D An 'excursion parameter(s State.	ENTRY POINT EP-A PWS ID 4100564 HILLS WATER ASSOCIATION period: Mart ZZ Month/Year Month/Year
1							•
						Print Nam Signature Date: _ <i>&</i>	Sh Mator
(No = N = Excursion) Total N's Send to DWP within 10 days after end of sampling period							

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: wwww.ohd.hr.state.or.us/dwp