

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Lincoln Agency: REGI</th></have<>	County: Lincoln Agency: REGI	
38	7.1				4	minimums	ENTRY POINT	
11	7.1				X	been met for this day?	EP-A	
20	7,8				Y		PWS ID 4100564	
27	7.6	5			7	BAY HILLS WATER ASSOCIATION		
	,							
						Camania	25 ET	
A .						Sample period: Month/Year		
				*		,		
				1		Number of excursions during this month:		
					2	(Over 9 exc Point and D An 'excursio	ursions in 6 months is a violation. Entry istribution excursions are cumulative). on' is any day in which the water quality s) fall below the minimum set by the	
						Refe	erence	
							Minimum Water Quality Parameter(s) as set by State:	
							pH 7.0	
i v								
			-					
							ne: John MacKown : On Moc Now	
(No = N = Excursion) Total N's Send to DWP within 10 days after end of sampling period								

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp