

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Lincoln Agency: REGI</th></have<>	County: Lincoln Agency: REGI	
"7	7,2				Y	minimums	ENTRY POINT	
12	7.3				Y	been met for this day?	EP-A	
19	7,24				y	ao docy	PWS ID 4100564	
27	7,2	ja			7	BAY HILLS WATER ASSOCIATION		
						Sample period: NOV ZZ Month/Year		
							, •	
						Number of excursions during this month: Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.		
					1			
						Refe	erence	
							Minimum Water Quality Parameter(s) as set by State:	
							pH 7.0	
· ·						Decree Annual Control		
, 1								
							*	
						Print Name: John MacKown Signature: John MacKown Date: / Dec 27		
No = N	No = N = Excursion) Total N's Send to DWP within 10 days after end of sampling period							

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: wwww.ohd.hr.state.or.us/dwp