

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Lincoln Agency: REGI</th></have<>	County: Lincoln Agency: REGI		
4	7.0				4	minimums been met for this day?	ENTRY POINT		
11	7-0				X		EP-A		
18	7.0				4		PWS ID 4100564		
29	7-2				1/	BAY HILLS WATER ASSOCIATION			
20	7.0				/				
1				in s		Sample	period: Dec ZZ		
				<i>P</i>		Month/Year			
						. ,	••		
					-	Number of excursions during this month: O  (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.  Reference			
					:				
	THE STATE OF THE S								
						Minimum Water Quality Parameter(s) as set by State:			
							p [		
-									
	***************************************								
-									
-						L			
						Print Name: John MacKown			
						Signature: John Mchoun			
						Date:/	JAN 23		
(No = N	(No = N = Excursion) <b>Total N's</b> Send to DWP within 10 days after end of sampling period								
Sampling period									

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: wwww.ohd.hr.state.or.us/dwp