

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	р	Н	Alk	Phos	Other	Y/N	< <have< th=""><th></th><th>County</th><th>: Clackamas A</th><th>ronove BE</th><th>CION 4</th></have<>		County	: Clackamas A	ronove BE	CION 4
1							minimun	ns		TRY P		
2		T				,·	been me		EN			
3							this day	?		EP-B		
4	7.	8	30.8			Υ			PWS	ID 410	0580	
5								NORT	H CLA	CKAMAS	COU	NTY WC
6												
7							Sar	mala na	riod.	June 20	23	
8							Sai	nple pe	110a		h/Year	
9										Work	7 007	-
10					-		Numb	er of ex	cursior	s during	this	month: 0
11	7.	7	35			Υ	(Over	9 excurs	ions in	6 months	isav	iolation. Entry
12		Ш										cumulative).
13		Щ					An 'exc	cursion'	is any c	lay in whi	ch the	water quality
14		$\perp \parallel$					-	eter(s) fa	all belov	v the min	imum	set by the
15		\perp					State.					
16												
17		Щ						Referer	nce			
18	7.	6	33.5			Υ						
19		\parallel								n Water (7	4
20		_						P	aramet	er(s) as s	set by	State:
21		\parallel							рН 📑	7.5		
22		\parallel									alinity)
23		\dashv	-							•		
24												
25	7.	/	32			Υ						
26		\dashv										
27		\dashv			-		F	Print Na	me:	Joe Rog	ers	
29		\dashv						Signatur		Je Q	0	W_
30		\dashv						Date & P	hone#	7-5-2	023	503-572-0129
31		\dashv					S	Send to [OWP wi	thin 10 da		ter end of
		_ -		\ T .	Г			ampling				
(No = N	1 =	⊏XC	ursion) I ota	ı N's	0						

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/