

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

| Day | рН | Alk | Phos | Other | Y/N |
|--------------------------------------|-----|------|------|-------|-----|
| 1 | | 0.00 | | | |
| 2 | | | | | |
| 3 | | | | | |
| 4 | | | | | |
| 5 | | | | | |
| 6 | | | | | |
| 7 | 7.6 | 34.2 | | | Y |
| 8 | | | | | |
| 9 | | | | | |
| 10 | | | | | |
| 11 | | | | | |
| 12 | | | | | |
| 13 | | | | | |
| 14 | 7.6 | 35.0 | | | Y |
| 15 | | | | | ' |
| 16 | | | | | |
| 17 | | | | | |
| 18 | | | | | |
| 19 | | | | | |
| 20 | | | | | |
| 21 | 7.6 | 32.0 | | | Y |
| 22 | | | | | |
| 23 | | | | | |
| 24 | | | | | |
| 25 | | | | | |
| 26 | | | | | |
| 27 | | | | | |
| 28 | 7.7 | 29.3 | | | Y |
| 29 | | | | | |
| 30 | | | | | |
| 31 | | | | | |
| No = N = Excursion) Total N's | | | | | D |

<<Have minimums been met for this day?

County: Clackamas Agency: REGION 1

ENTRY POINT

EP-B

PWS ID 4100580

NORTH CLACKAMAS COUNTY WC

Sample period: _

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

Minimum Water Quality Parameter(s) as set by State:

рН 7.5 25.0 (Alkalinity) Alk

Print Name: Jos

Signature: Date & Phone#

Send to DWP within 10 days after end of

sampling period