

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N	< <have< th=""><th>County: Clackamas Agency: REGION 1</th></have<>	County: Clackamas Agency: REGION 1	
1						minimums	ENTRY POINT	
2						been met for	EP-B	
3						this day?		
4							PWS ID 4100580	
5	7.71	30.9			$ \mathcal{X} $	NORTH CLACKAMAS COUNTY WC		
6							,	
7	-0					Sample period: 5/2024 Month/Year		
8							Month/Year	
9								
10						Number of ex	ccursions during this month: 🙇	
11						(Over 9 excur	sions in 6 months is a violation. Entry	
12	7.63	31.4				Point and Distribution excursions are cumulative).  An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.		
13			<u> </u>					
14								
15		<u> </u>				State.	•	
16								
17						Reference		
18								
19	7.74	32.0			$\perp$	i i	Minimum Water Quality	
20			ļ			F	Parameter(s) as set by State:	
21							pH 7.5	
22							Alk 25.0 (Alkalinity)	
23								
24		<u> </u>				ļ	*	
25	77/	<u></u>			$\left  \cdot \right $			
26	14.45	31.7						
27			<u> </u>			Print Name: Jos Royers		
28	ļ				$\sqsubseteq$	Signature:		
29			ļ	-		Date &	Phone#: <u>&amp;-/-Z4_505-572-0/Z</u> 9	
30							DWP within 10 days after end of	
31	<u></u> _					sampling period		
No = N = Excursion) <b>Total N's</b>					0	·	- ·	

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/