

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	8.06	29.5			4
2					- (
2 3 4 5 6 7					
4		_			
5					
6	8.20	35.4			Y
7					1
8					
10 11 12 13 14					
11					
12					
13					
14					
15 16					
16	8.02	37.2			Y
17					1
18 19					
19		1984			
20 21 22 23 24					
21	8.24	26.1			4
22					,
23					
25					
26					
27					
28					
29					
30					
31					
No = N = Excursion) Total N's					

<<Have minimums been met for this day?

County: Clackamas Agency: REGION 1 **ENTRY POINT**

EP-B

PWS ID 4100580

NORTH CLACKAMAS COUNTY WC

Sample period: $\frac{2/2025}{Month/Year}$

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference		
		iter Quality as set by State:
pH Alk	7.5 25.0] (Alkalinity)
·		•

Print Name: Bret Bienerth
Signature: The Disnerth

Date & Phone#: 3-3-25 971-356-6943

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/