

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рΗ	Alk	Phos	Other	Y/N
1		-rougekernesser and e			
2	8.2	25.0			Y
2					
4					
5 6	8.3	25.7			4
6					,
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17	8.0	27.6			7
18					1
19					
20					
21					
22					
23					
24					
25					
26					
27					
28					
29	8.1	29.0			Y
30					,
31					
No = N = Excursion) Total N's					Ø

Number of excursions during this month: _______

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference
Minimum Water Quality Parameter(s) as set by State:
pH 7.5 Alk 25.0 (Alkalinity)
Print Name: Steve Prestwood Signature: Manual Date & Phone#: 4-4-25 971-295-1052 Send to DWP within 10 days after end of

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

sampling period