

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N	
1						
2	8.0	32.6			1	
3						
4						
5						
6						
7						
8				20		
9	7.9	34.0			У	
10	•				'	
11						
12						
13						
14						
15						
16	7.8	33.9			Y	
17					ì	
18						
19						
20						
21						
22						
23	8,D	32.1			4	
24 25						
25					Si 14	
26						
27						
28						
29	7.9	32.9			4	
30					À	
31						
No = N = Excursion) <b>Total N's</b>						

< <have< th=""><th>County: Clackamas Agency: REGION 1</th></have<>	County: Clackamas Agency: REGION 1					
minimums	<b>ENTRY POINT</b>					
been met for this day?	EP-B					
PWS ID 4100580						
NORT	H CLACKAMAS COUNTY WC					
	7 /200					
Sample pe	riod: July/2025					

Number of excursions during this month: (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the

Month/Year

Minimum Water Quality
Parameter(s) as set by State:

pH 7.5
Alk 25.0 (Alkalinity)

Print Name:	Steve	Presto	rood
Signature:	the 1	whil	
Date & Phone	e#: 8-4-	25 971	29.5-105)

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

State.