

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/I
1					
2					
3					
4	7.84	36.5			Y
5	,	ľ			1
6					
7					
8					
9					
10					
11	7.51	37.3			Y
12					1
13					
14					
15					
16					
17	7,75	37.5			Y
18					(
19					
20					
21					
22					
23					
24	7.84	26.5			У
25					7
26					
27					
28					
29					
30					
31					
10 = V	1 = Exc	cursion) Total	N's	Ø

<<Have
minimums
been met for
this day?</pre>

County: Clackamas Agency: REGION 1

ENTRY POINT

EP-B

PWS ID 4100580

NORTH CLACKAMAS COUNTY WC

Sample period: 9/2025
Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Print Name: Steve Prestuood

Signature: Ste Whit

Date & Phone#: 10-2-25 971-195-1051

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/