

## Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

Day		Alk	Phos	Sili	Y/N
-1	7.4	<u> </u>		Decystropes	Υ
2	7.3				Y
3	7.2				Υ
4	Plar	nt Off			
5	Pla	-			
6	7.3				Υ
7		plant off			
8	7.2	33			Υ
9	7.2				Υ
10	7.2				Υ
11	7.2				Υ
12	7.2				Υ
13	7.2				Υ
14	7.2	30			Υ
15	7.2				Υ
16	7.2				Υ
.17	7.4				Υ
18	7.3				Υ
19	7.2		•		Υ
20	7.3				Y Y
21	7.3	30			Υ
22	7.3				Υ
23	Plant	Off			
24	7.2				Υ
25	7.2				Υ
26	7.2				Y
27.	7.2				Υ
28	7.2	36			Υ
29	7.2			`	Y
30	7.2			,	Υ
31					
0 = N	= Exc	ursion)	Total	N's	

(No = N = Excursion) Total N's 0

< <have< th=""></have<>
minimums
been met for
minimums been met for this day?

County: Curry

Agency: REGI

## **ENTRY POINT**

EP-A

PWS ID 4100670 PORT ORFORD, CITY OF

Sample period: November 2023

Month/Year

Number of excursions during this month: 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

	-Reference
	Minimum Water Quality Parameter(s) as set by State:
	pH 7.2
Processing and Street Street,	

Send to DWP within 10 days after end of sampling period

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp