

Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	Hq	Alk	Phos	Other	YIM	< <have< th=""><th>County: Coos Agency: REGION 2</th></have<>	County: Coos Agency: REGION 2	
1	7.4	54			7	minimums	ENTRY POINT	
2	7.4	.54			~	been met for		
3	7.5	53			V	this day?	EP-A	
4.	7,5	58		<u> </u>	γ		PWS ID 4100672	
5	-7.5	57		<u> </u>	γ		POWERS, CUTY OF	
රි	7.5	56			γ	Ì		
7	7.6	58.			У	Sample period: <u>November 2014</u> Month/Year		
8	7.6	57	1	}	У			
9	7.6	59		-	γ			
10	7.1	57			γ	Number of excursions during this month:		
77	7.7	:62			γ	(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are		
12	7,8	60			γ			
13	7,7	60			l y	cumulative). An 'excursion' is any day in which the		
14	7.5	52			ŀγ	water quality parameter(s) fall below the minimum set by the State.		
15	7.6	54			y			
16	7.7	55			у			
17	7.7	56		•	Ϊ'n			
18	7.5	48	-	<u> </u>	γ			
19	7.5	48			Y		Minimum Water Quality	
20	7.5	.53			Y		Parameter(s) as set by State:	
21	7.5	46			Y		pH 7.2	
22	7.7	55	-		lγ		the same of the sa	
23		46			Y		Alk 34.0 (Alkalinity)	
24		43			Y			
25	3	46			Y			
	7.5	49			ly	1		
27	7.5	46			У	Dring P	Marane	
	7.6	50.			X	Print Name: Signature: Date & Phones:		
4,200	7.5	145			J			
-	75	145	Salar Sa		X	1 <u>\$</u>		
31	territoria de la constanti de				 	Send to DVVP within 10 days after end of sampling period		
No = N = Excursion) Total N 's				al N's	0	7 3G1 AQ1	ing hanga	

CHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Websits: http://healthoregon.org/dwp/