

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1	7.2				V
2	7.2 7.3 7.3 7.2	-			4
3	7,3				Y
4	7.2	/			F
2 3 4 5 6 7					7 7 7 9
6	7.2				4
	7.3 7.3 7.2				7
8	7.3				4
9	7.2				4
10 11 12	7.2				V
11	7.3				Ý
12	7.4				Υ
13	7.5				У
14	7.5				7
15	7.5				4
16	7.6				4
17	7.5		1.1		4
18	OFF				
18 19	7.7				7
20 21	7.7		-		4
21	7.7	e			y
22 23 24	7.6e				7
23	7.7			1	4
	7.8				4
25	7.8				4
26	7.8				4
27	7.8				4
28	7.8				4
29	7.7				7
30	7.7	141			4
31					
No = N = Excursion) Total N's				1	

< <have< th=""><th>County: Columbia Agency: REGION 1</th><th></th></have<>	County: Columbia Agency: REGION 1	
minimums	ENTRY POINT	
been met for this day?	EP-A	
	PWS ID 4100792	
	SCAPPOOSE, CITY OF	
Sample pe	eriod: Nov 2023	

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Month/Year

Reference
Minimum Water Quality Parameter(s) as set by State:
pH 7.2 Alk (Alkalinity)
Print Name: Darry Sykes
Signature: Darry Lykes
Date & Phone#: \2/6/2023 \
Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/