

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	7.3				\
	7.2	A			1
3	7.3				4
2 3 4 5 6	7.3	105			Y
5	73				1
6	7.2				7
7	7.2				1
8	7.3				7
9	7.3				4
10	7.7				4
10 11 12	7.5				7
12	7.2				4
13	7.2				7
14	7.5		*		4
15	7,5	111			4
16	7.3			1	7
17	7.5				7
18	7.7				4
19	7,2				9
20	7.3	2.55			y
21	7.5				14
22	7.5				1
23	7.5				4
24	7.5				Y
25	7.5				4
26	7.4				7
27	7,5				14
28	7.5	1			Y
29	7,21				Y
30	7.5	110		-	4
31					
Vo =	N = Ex	cursic	n) Tot	al N'e	1

< <have< th=""><th>County: Columbia Agency: REGION 1</th></have<>	County: Columbia Agency: REGION 1
minimums	ENTRY POINT
been met for this day?	EP-B
	PWS ID 4100792
w 2	SCAPPOOSE, CITY OF
Sample pe	eriod: SEPIEMBER/2021 Month/Year

Number of excursions during this month: ______

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

		ter Quality as set by State:
рН	7.2]
pH Alk	90.0	(Alkalinity)

Print Name: 1			
Signature:	Darm	in Dyles	
Date & Phone	#: 10/8	1/202/503-369-0297	

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/