

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	7.6				V
2	7.6	109			(
3	7.7				4
4	7.7				4
5	7.7				1
6	Fib	^			
7	7.6	,			
8	7.6	XXX X			7
9	7.7				1
10	7.7				4
11	7.6	1111			Y
12	7.4				Y
13	7.4				4
14	7.4				4
15					,
16	7.5				4
17	70				1,
18 19	7.8				7
20	7.7				X
21	7.8	111			Y
22	716	[[[У
23	7.6				Y
24	77				Y
25	7.7				<u> </u>
26	7.6				У.
27	7 4				4
28	スフ	108			4
29	マラ				4
30	7.4				X
31					7
	= Fxc	ursion)	Total	NIC	ch.

<<Have minimums been met for this day?

County: Columbia Agency: REGION 1

ENTRY POINT

EP-B

PWS ID 4100792 SCAPPOOSE, CITY OF

Sample period: SEFT ZOZZ

Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

		ater Quality) as set by State:
pH Alk	7.2 90.0	(Alkalinity)

Print Name: Darry Sykes
Signature: Darry Sykes

Date & Phone#: 10/6 2022 503-369-0297

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

