

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	7.5				10
2	7.4				4
3	OFF	_			
4	OFF	-			
5	7.5				y
6	7.5				y
7	OFF				
8	7.4				4
9	7.4	136			4
10	O.F.F				/
11	7.5				y
12	7.6				4
13	7.7				4
14	7.5				4
15	OFF				
16	7.4				4
17	OFF				
18	OFF				1 11
19	OFF				
20	OFF				
21	7.4				4
22	7,21				4
23	7.5				4
24	off				
25	off				
26	7.4				У
27	7.5				Y
28	7.5				Y
29	7.5				Y
30	7.4				Y
31	off				/
No = N	V = Exc	ursion) Tota	l N's	0

County: Columbia Agency: REGION 1
ENTRY POINT
EP-B
PWS ID 4100792
SCAPPOOSE, CITY OF
Sample period: Aug 2024
Month Wear

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

		ater Quality) as set by State:
рН	7.2	
Alk	90.0	(Alkalinity)
AIR	30.0](Alkallilly)

Signature: 1/6/2024 503-369-0297

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/