

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	7,5				4
3	Off	-			_
3	721				4
4.	7.5				y
5	7.5				4
6	72				4
7	7.5	131			4
8	7.7				Y
9	OFF				
10	7,6				Y
11	7.6				4
12	OFF	-			
13	7.6				4
14	7,6				4
15	7.6	128			y
16	7.6				4
17	7.6				4
18	7.6				Y
19	7.5				7
20	7.5				Y
21	7.60				4
22	7.6	128			4
23	7.5				4
24	7.6				4
25	7.3				7
26	7.5				4
27	7.4				y
28	7.4				4
29	7.6	137			4
30	7.5				4
31	7.4				4
No = N = Excursion) Total N's					1

<<Have minimums been met for this day?

County: Columbia Agency: REGION 1

ENTRY POINT

EP-B

PWS ID 4100792

SCAPPOOSE, CITY OF

Sample period: OCIOBER 2024

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

Minimum Water Quality Parameter(s) as set by State:

7.2 pH Alk 90.0 (Alkalinity)

Print Name:

Signature:

Date & Phone#: \\

503-369-0297

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/