Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

				· · ·	-	bei ime i	2011031011 CO
Day	pН	Alk	Phos	Other	Y/N	<< Have	County: Wasco
1	7.3		0.6		У	minimums	
2						been met for	MICKE
3						this day?	WICKS
4						***************************************	•
5							
6							PWS
7							THE D
8	7.6		0.4	, i	у		
9							Sample period: Janu
10						N	umber of excursions du
11							
12						Over 9 ex	cursions in 6 months is
13						1	n excursions are cumulo
14						1	ich the water quality p
15	7.4		0.5		У		et by the State.
16							
17						Referenc	ie
18] -	
19							Minimum Water (
20]	Parameter(s) as se
21] }	
22	7.5		0.5		у		pH 7.0
23							
24							PO4 0.4 (mg/
25	•						
26							
27							
28						Print	t Name: Tyler Mitchell
29	7.6		0.4		у	 Signature:	T. 1:-1
30						Jignature:_	Hymn
31						Date & Pho	one: 4-Feb-2025;
(No = N	= Excur	sion)	To	otal N's	0		

Agency: REGION 1

ENTRY POINT

EP-A

ID 41-00869 **DALLES, CITY OF**

uary 2025

uring this month: 0

a violation. Entry Point and lative). An 'excursion' is any parameter(s) fall below the

Reference	
Minimum Water Quality Parameter(s) as set by the State:	
pH 7.0	
PO4 0.4 (mg/L, Orthophosphate)	

541-298-2248 x 5010

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp