## OHA

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

					F I			_
Day	рΗ	Alk	Phos	Other	Y/N	<< Have	County: Wasco	F
1						minimums		
2	7.4		0.5		Υ	been met for	WICKS EN	17
3						this day?	VVICKS EN	1
4							E1	<b>n</b>
5							El	
6						]	PWS ID	4
7							THE DALL	.E
8							Sample period: July 202	-
9	7.4		0.5		Υ		Sample period: July 202	Э
10						N	umber of excursions during	t
11								
12						Over 9 exc	cursions in 6 months is a vic	oli
13						Distribution excursions are cumulative).		
14							ich the water quality parai	•
15						minimum s	et by the State.	
16	7.5		0.5		Υ			
17						Referenc	ce .	
18						]   -		
19							Minimum Water Qua	al
20							Parameter(s) as set k	Ŋ
21						]		
22							pH 7.0	
23	7.5		0.5		Υ			
24						]	PO4 0.4 (mg/L, O	rt
25							<del></del>	
26							<u> </u>	
27								
28						Print Name	e: Tyler Mitchell	,
29						Signature:	TIMETIN	1
30	7.4		0.5		Υ		M/M	+
31						Date & Pho	one:/ 8-Aug-25	
(No = N	= Excur	sion)	T	otal N's	0	]	•	
						ME	Sand to DWD within 10 day	

Agency: REGION 1

## TRY POINT

P-A

41-00869 ES, CITY OF

this month:

lation. Entry Point and ). An 'excursion' is any neter(s) fall below the

Reference						
Minimum Water Quality Parameter(s) as set by the State:						
pH 7.0						
PO4 0.4 (mg/L, Orthophosphate)						

541-298-2248 x 5010

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp