Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

<< Have

this day?

minimums

been met for

1 2 3 4 5 6 7 8 9 10 11	рН	Alk	Phos	Other	Y/N
3 4 5 6 7 8 9 10				OFF	
4 5 6 7 8 9 10				OFF	
5 6 7 8 9 10 11				OFF	
6 7 8 9 10 11				OFF	
7 8 9 10 11				OFF	
8 9 10 11				OFF	
9 10 11				OFF	
10 11				OFF	
11				OFF	
				OFF	
12				OFF	
				OFF	
13				OFF	
14				OFF	
15				OFF	
16				OFF	
17				OFF	
18				OFF	
19				OFF	
20				OFF	
21				OFF	
22				OFF	
23				OFF	
24				OFF	
25				OFF	
26				OFF	
27				OFF	
28				OFF	
29				OFF	
30				OFF	
No = N = Excursion)		ion)	To	tal N's	0

Well inspected daily. Samples collected when well is operating at time of inspection NR = Well not running during inspection

County: Wasco

Agency: REGION 1

Lone Pine Well **ENTRY POINT**

EP-B PWS ID 41-00869 THE DALLES, CITY OF

Sample period: April 2021

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference
Minimum Water Quality Parameter(s) as set by the State:
pH TBD
PO4 0.4 (Orthophosphate)
Assessment Monitoring

Print Name: Larry McCollum

Signature: /

Date & Phone: 05 May 2021; 541-298-2248 x 5000

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp