## OHA

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	V/N
1	<u> </u>	, 1111		OFF	.,
2				OFF	
3				OFF	-
4				OFF	
5				OFF	
6				OFF	-
7				OFF	<b></b> -
8				OFF	
9				OFF	
10				OFF	<u> </u>
11				OFF	
12				OFF	
13				OFF	
14				OFF	
15				OFF	
16				OFF	
17				OFF	
18				OFF	
19				OFF	
20				OFF	
21				OFF	
22				OFF	
23				OFF	
24				OFF	
25				OFF	
26				OFF	
27				OFF	
28				OFF	
29				OFF	
30				OFF	
31		,		OFF	
(No = N =	= Excurs	ion)	To	tal N's	0

31 OFF
(No = N = Excursion) Total N's
Well inspected daily. Samples collected when
well is operating at time of inspection

OFF = Well off for the season

DNR = Did not run this 24 hr period

<< Have
minimums
been met for
this day?

County: Wasco

Agency: REGION 1

Lone Pine Well
ENTRY POINT

EP-B
PWS ID 41-00869
THE DALLES, CITY OF

Sample period:

December 2021

Number of excursions during this month:

0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Referen	осе
	Minimum Water Quality Parameter(s) as set by the State:
	pH 7.8
	PO4 0.4 (Orthophosphate)

Print Name: Larry-McCollum

Signature: \_@

Date & Phone: 04 January 2022; 541-298-2248 x 5000

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp