## **OHA**

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

			LCa			Jei Muie (		
Day	рН	Alk	Phos	Other	Y/N	<< Have	County: Wasco	Agency: REGION 1
1						minimums	Lone Pine Well ENTRY POINT	
2						been met for		
3						this day?		KI POINI
4						1		EP-B
5	8.2		0.6		у	_		
6	8.1		0.7		У		PWS I	D 41-00869
7	8.0		0.6		У		THE DA	LLES, CITY OF
8			<u> </u>				Sample period: May 2	2025
9	8.0		0.5		У			
10		ļ	ļ			. N	umber of excursions duri	ng this month: 0
11			ļ			_		
12						(Over 9 ex	cursions in 6 months is a	violation. Entry Point and
13	8.1		0.5		У	Distributio	n excursions are cumulat	ive). An 'excursion' is any
14	8.0		0.5		У	day in which the water quality parameter(s) fall below the		
15						minimum s	set by the State.	
16	8.2		0.5		У			
17	8.2		0.6		у	Referenc	ce	
18						]		••
19	8.1		0.5		У	_	Minimum Water Q	
20						4	Parameter(s) as se	t by the State:
21	8.0		0.5		У			
22	8.1	<u> </u>	0.5		У		pH 7.8	
23	Out of Service							
24		Out of Service				_	PO4 0.4 (Ortho	ophosphate)
25	Out of Service				4		·	
26	Οι	Out of Service				_  L		***************************************
27	Out of Service					4		
28	Out of Service				1	Print Name: Tyler Mitchell Signature:		
29	Out of Service							
30	Out of Service							
31	Ot	Out of Service				Date & Ph	one: 9-Jun-25	541-298-2248 x 5010
(No = N = Excursion) Total N's 0								
Mall land		latte Care		لين لمحجما			Sand to DWD within 10 a	lave after the

Well inspected daily. Samples collected when well is operating at time of inspection

Send to DWP within 10 days after the end of the sampling period