OHA

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

				u		pei ituie
Day	рН	Alk	Phos	Other	Y/N	<< Have
1						minimums
2	8.0		0.5		У	been met for
3						this day?
4	8.0		0.5		У	
5	8.1		0.5		У	
6]
7	8.1		0.5		У	1
8	8.2		0.6		У	1
9	8.1		0.5		У	
10	8.1		0.6		У	
11	8.1		0.7		У]
12						(Over 9
13	8.2		0.5		У	Distribut
14	8.2		0.5		У] day in v
15	8.1		0.6		У	minimun
16	8.1		0.6		У	
17						Refere
18	8.1		0.5		У	
19						
20	8.2		0.5		У]
21	8.0		0.6		У	
22	8.2		0.5		У	
23	8.1		0.5		у	
24	8.1		0.5		У	
25	8.0		0.6		У	
26	8.0		0.7		у] [
27						
28						Print Na
29] Signatur
30	8.1		0.4		У	Signatur
(No = N = Excursion)			T	otal N's	0	Date & I

Well inspected daily. Samples collected when well is operating at time of inspection

County: Wasco

Agency: REGION 1

Lone Pine Well ENTRY POINT

EP-B

PWS ID 41-00869 THE DALLES, CITY OF

Sample period: June 2025

Number of excursions during this month:

er 9 excursions in 6 months is a violation. Entry Point and ribution excursions are cumulative). An 'excursion' is any in which the water quality parameter(s) fall below the imum set by the State.

Referen	ce
	Minimum Water Quality Parameter(s) as set by the State:
	pH 7.8
	PO4 0.4 (Orthophosphate)

t Name: Tyler Mitghell

e & Phone:

7/10/2025

541-298-2248 x 5010

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp