OHA

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other		<< Have	County: W	/asco	Agency: REGIO	N 1
1	8.1		0.5		Υ	minimums	Lone Pine Well			
2	8.2		0.7	<u> </u>	Ϋ́	been met for				
3						this day?		ENTF	RY POINT	
4							l	ر مسو		
5			<u> </u>	<u> </u>				E	P-B	
6	8.1		0.5		Υ		PWS ID	41-008	369	THE
7	8.1		0.5		Υ			DALLE	S, CITY OF	
8							Canada nastati		-	
9	**********						Sample period:	July 202	5	
10						N	umber of excursio	ons during	this month:	0
11	***************************************									
12						Over 9 ex	cursions in 6 mo	nths is a	violation. Entry	Point and
13						Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum				
14										
15						set by the S	State.			
16	8.1		0.6		Υ					
17		ļ				Referenc	:e			
18	8.2		0.5		Y					
19							Minimum Wa	ater Qua	ality	
20							Parameter(s)	as set k	y the State:	
21						1		1		
22		ļ				1 1	pH 7.8			
23	<u></u>					4		l		
24	8.0	ļ	0.5		Υ	4	PO4 0.4	(Orthopl	nosphate)	
25	8.1	<u></u>	0.5		Υ	4				
26	8.1		0.6		Y	ļ L				
27			 			4		4	1	
28						Print Name	e: Tyler Miterell	// 、	-t 1	
29	<u> </u>		 	 		- Signature:		-th	\mathcal{M}	
30					 	Date & Pho		· · · · · ·	F44 200 224	0 5040
31		<u> </u>			-	Date & Ph	one: 8-Au	g-25	541-298-224	8 ext 5010
(No = N		•		otal N's	L	J	Cond to DWD wit	la de la composición	6 Al	

Well inspected daily. Samples collected whenSend to DWP within 10 days after thewell is operating at time of inspectionend of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp