OHA

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	<< Have	County: Wasco	Agency: REGION 1
1						minimums	Marks Well	
2	W					been met for	ENTRY POINT	
3	e					this day?	ENII	RY POINT
4	-1					_		EP-D
5								
6	o					PWS ID 41-00869		
7	f					THE DALLES, CITY OF		
8	f						Sample period: Augus	t 2025
9						_	outspic perious stugue	
10	d					Number of excursions during this month: 0		
11	e							
12						(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.		
13	t		ļ					
14	0							
15	m							
16	е .							
17	¢					Reference		
18	h					_]		
19	а					Minimum Water Quality Parameter(s) as set by the State:		
20	n							
21]							
22	a		<u> </u>			pH 7.6 PO4 0.4 (Orthophosphate)		
23	1							
24								
25	f - a							
26	a 1							
27	Ì							
28	u					Print Name: Dave Anderson Signature:		
29	Γ							
30	e							
31						Date & Pho	one: 5-Sep-25	541-506-2008
(No = N = Excursion) Total N's 0								

Well inspected daily. Samples collected when well is operating at time of inspection

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone (971) 673-0405 Website: http://healthoregon.org/dwp