## **OHA**

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N	<< Have	County: Wasco	Agency: REGION 1
1						minimums	Marks Well	
2						been met for		TRY POINT
3						this day?	EIN	INTPOINT
4	60.000.00							EP-D
5								
6						PWS ID 41-00869		
7							THE D	ALLES, CITY OF
8			<u> </u>			_	Sample period: Sep	tember 2025
9	W		ļ		ļ			
10	e					Number of excursions during this month: 0		
11						_		
12						(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.		
13	l i		<u> </u>					
14	l i		<u> </u>					
15	-		ļ	<u> </u>				
16	5				<u> </u>			
17	t					Referenc	ce	
18	a			<u> </u>			Minimum Water	Quality
19	n				+	Minimum Water Quality Parameter(s) as set by the State:		
20	d b					-	Parameter(s) as s	et by the State:
21	٧.		<u> </u>		<u> </u>	pH 7.6 PO4 0.4 (Orthophosphate)		
22	- '				+			
24								
25					<u> </u>	-	10/1	nophoophato)
26					1			
27					<b>†</b>	<b>-</b>		
28			<del> </del>	<u> </u>	1	Print Nam	e: Tyler Mitøhell	A
29			<del>                                     </del>			Signature:		
30	-			<u> </u>				
(No = N = Excursion)								
184-11 to an extend delth. Computer collected subset								

Well inspected daily. Samples collected when well is operating at time of inspection

Send to DWP within 10 days after the end of the sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp